

TO :

Date : 2025/12/04

End of Life Notice

We would like to notify that ABC Taiwan Electronics will discontinue the production of the following from now on. The reason is the market demands does not reach the economic scale of production.

Affected Products :

ABC's DWG NO.	Last Time Buy	Last Shipment	Replacement	Substitution Level	Remark
DR111600032A	From now on	From now on	/	4	/
PA1016331K2A	From now on	From now on	/	4	/
PH2128680K2AP02	From now on	From now on	/	4	/
PV10205R0Y2A	From now on	From now on	/	4	/
TB0703-L	From now on	From now on	/	4	/
TF3119102Y2A	From now on	From now on	/	4	/
RB05088R0M3A	From now on	From now on	/	4	/
RB05083R3M2A	From now on	From now on	/	4	/
RB0710681K2A	From now on	From now on	/	4	/
RB0710102K2A	From now on	From now on	/	4	/
RB0906102J2A	From now on	From now on	/	4	/
RC0507102K3A	From now on	From now on	/	4	/
RC0507102J3B	From now on	From now on	/	4	/

Last Time Buy (LTB) option :

ABC Taiwan Electronics will support Last Time Buy (LTB) orders received on or before the date listed above (LTB Date). LTB orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unexpected events might prevent ABC Taiwan Electronics from supporting partially or fully on the LTB orders. If such an event occurs, we will notify you of our best support plan as soon as possible.

Please accept our sincere apologies for any inconvenience it may cause , and thank you very much for your understanding.

Best Regards

ABC Taiwan Electronics Corp.

Francis Fan

Francis Fan

Substitution Level

- 1.=Package and characteristics are mostly same or better, not necessary to change other circuit to replace.
- 2.=Package and characteristics are mostly same or better, but some modification of the other circuit is necessary
- 3.=Characteristics are same or better, but, package/pin arrangement are different, so the other circuit modification is necessary.
- 4.=Other reason --- No direct match of package and characteristics for this product, we recommend finding other components for replacement.